



Installation failure cases in 2024



Service Operation Team 2024.06.30

Contents



	Page
□ Network / Analog Camera	
1 Water leaks in XNP-9250R camera bodies	3
2 Problem of camera audio use setting cancellation after reboot	4
3 The bullet camera rear assy damaged within 1 month of its installation	5
4 FAN noise of the housing-integrated PTZ camera	6
5 Failure to detect loitering events within the IVA-designated area	7
□ NVR/DVR	
6 The NVR password reset button not working	8
7 Voltage difference between the NVR cover and the building ground	9
8 NVR DDNS connection failure	10
9 HDDs not detected after NVR delivery	11

Water leaks in XNP-9250R camera bodies


No.	# 1	Product Line	Network Camera
Product(Model)	XNP-9250R	Keyword	Reverse direction, Water leaks, Submersion, IP rating

1. Installation Cases

- Hanwha Vision's PTZ camera was installed for surveillance outside the office building.
- The camera was installed in reverse direction upon separate request from the end user.

2. Symptoms

- When disassembling cameras which couldn't be turned on, traces of water leaks were found in the camera bodies.




3. Causes

- Water couldn't be discharged from the PAN rotation bearing part due to a camera installed in the reverse direction, which made it difficult to guarantee its waterproofing. As a result, water remained in the part.
- The waterproof and dustproof rating of XNP-9250R is IP66 (spraying water, dripping water)
- Protection against water not discharged is guaranteed with IP67 (immersion), not with IP66.



4. Measures

- It is recommended to install the camera in the correction direction.
- The reference point for product installation is the logo printed on the product, which must be displayed properly as shown in the photo below.



< e.g. product installation in the correct direction >

Problem of camera audio use setting cancellation after reboot


No.	# 2	Product Line	Network Camera
Product(Model)	XNP-6320	Keyword	Profiles, Enabling audio use, Setting cancellation

1. Installation Cases

- The network camera was installed for security surveillance (including voice notification) in general office buildings

2. Symptoms

- Rebooting the system after changing the camera setting to use audio (enabling the 'Audio in' option in the profile)
- The 'Audio in' option became unchecked after reboot.



3. Causes

- When the system rebooted after changing the camera settings, the settings of the last connected device (NVR/SSM, etc.) were retrieved in the process of restoring the settings. As a result, the problem of setting cancellation occurred.

4. Measures

- (1) Refer to the path below to first enable the audio use item on the storage device, then
- (2) Then enable the audio input item for each camera profile.

Record setup

Path: Settings → Save → Save Settings → Audio

Total bitrate (limit/max) 396.0 / 400 Mbps

Apply to other channels

CH	Camera name	IP address	Continuous recording	Event recording	Continuous recording	Event	Audio
1	CAM 01	192.168.1.10	Full	Full	Full frame	8 M	Off
2	CAM 02	192.168.1.11	Full	Full	5 s	6 M	On
3	CAM 03	192.168.1.13	Full	Full	5 s	20 M	Off
4	CAM 04	192.168.1.14	Full	Full	5 s	5 M	Off
5	CAM 05	192.168.1.14	Full	Full	5 s	5 M	Off

The bullet camera rear assy damaged within 1 month of its installation

No.	# 3	Product Line	Network Camera
Product(Model)	KNO-V2020R	Keyword	Electrically-drive tools, Rear Assy, Joint damage

1. Installation Cases

- The network camera was installed for security surveillance in general office buildings

2. Symptoms

- There was a risk of the camera falling due to damage to the joints of its rear assy within 1 month after its installation.



3. Causes

- Cracks caused by fastening the fixing screw with an electrically-drive tool.
- Cracked products randomly repaired and installed with instant adhesive.



4. Measures

- Use manual tools to prevent torque overload when tightening bolts.
- In particular, do not use electrically-drive tools to secure areas where plastic and metal meet.

FAN noise of the housing-integrated PTZ camera

No.	# 4	Product Line	Network Camera
Product(Model)	XNP-L6252H	Keyword	Housing, FAN noise, Bracket, Recessed mounting

1. Installation Cases


- The housing-integrated network PTZ camera was installed for security surveillance within religious facilities

2. Symptoms

- Severe noise and ceiling vibration occurred during fan operation due to heat generation inside the camera.

3. Causes

- Improper product installation: Outdoor housing camera installed in the form of recessed mounting in the indoor ceiling
- The housing arbitrarily modified (laser processed) for camera installation in the form of recessed ceiling mounting on site
- The Fan noises from FAN operation along with the ceiling vibrating sound from loosened mechanical operating parts



< Actual installation view >

4. Measures

- Be sure to check the product's purpose and manual before installing it, and arbitrary modifications are subject to limited service warranty.
- When selecting a product, refer to the Product Naming Rule on the website
- H: Housing models cannot be installed by recessed mounting in an indoor ceiling.

Features

• A : Revision	• B : Black Color	• C : Counting or Corner	• D : Dual Eye
• E : Explosion Proof or PoE extender	• F : Flush or SFP LC (Fiber Channel)	• G : Government	• H : Housing

Failure to detect loitering events within the IVA-designated area


No.	# 5	Product Line	Network Camera
Product(Model)	XNF-9013RV	Keyword	IVA, Loitering

1. Installation Cases

- The IVA loitering detection option was enabled after installing the camera, XNF-9013RV, for the security around the building

2. Symptoms

- Loitering detection was set by specifying the IVA area, but the event was not detected.
- Conditions: Object-Person, Categories-Loitering, minimum duration (s)-minimum value (10 seconds)
- Result: The event was recognized as 'motion detection' rather than 'loitering detection'.



3. Causes

- Since the object to be detected does not show its continuous movement, it does not meet the loitering detection conditions.
- In the following cases, the target loitering object became undetectable as the system considered it disappeared.
 - When the target object didn't move for a certain period of time
 - When the target object overlapped another object
 - When the environment was complex because there was a moving object in the vicinity of the target object

4. Measures

- Set both 'Loitering' and 'Enter' conditions for IVA

The NVR password reset button not working

No.	# 6	Product Line	NVR
Product(Model)	XRN-1610S	Keyword	Password, Reset

1. Installation Cases


- The site Admin was changed after installing the NVR for commercial building monitoring.

2. Symptoms


- It was impossible to access the system with admin privileges due to the lost password
- It was impossible to reset the password by pressing the small hole on the back of the system with a sharp tool.

3. Causes

- The [Password Reset] button on the back of the product was damaged by repeatedly pressing it with excessive pressure.
- The button can be considered to be damaged in the following cases:
 - a. If you do not feel the button being pressed when you use a tool to press the part where the reset button is located.
 - b. If you hear the sound of separated parts moving when you lift the product.



[Reset button on the back of the product]



[Reset button broken and separated]

4. Measures

- Press the [Password Reset]] button with a sharp tip for about 15 seconds with moderate force.
- If there is no response when pressing the button with a tool, contact a designated repair shop for its repairs.

Voltage difference between the NVR cover and the building ground

No.	# 7	Product Line	NVR (models with adapters)
Product(Model)	QRN-830S/430S	Keyword	Power, Ground, Short circuit

1. Installation Cases

- The NVR models were installed in office.


2. Symptoms

- There is a voltage difference between NVR Cover and building ground
- The neutral-to-earth voltage (NEV) is mistaken for leakage voltage

* Neutral-to-Earth Voltage: It is an invalid power voltage caused by the potential difference between the neutral terminal and the earth when the earth is not connected (this phenomenon is not a defect in the product)



[NEV between Adapter Neutral terminal and GND]




3. Causes

- The NVR ground terminal was not connected.

4. Measures

- Follow the installation guide: Use the Ground terminal for ground connection.



2	Ground Connection	Port for connecting a separate ground cable. ■ For safe handling of the device, please add a ground wire.
----------	-------------------	--

NVR DDNS connection failure

No.	# 8	Product Line	NVR
Product(Model)	XRN-420S	Keyword	External network connection error, DDNS connection failure

1. Installation Cases

- There were an external network connection error and an DDNS connection failure.

2. Symptoms

- The system was connected to the network, but DDNS was not accessible.




3. Causes

Quick connect(UPnP) Failed to find a router. Check the router's configurations.

- "Auto" used for NVR DNS server IP address + error in Router's DNS IP setting

[Incorrect Procedure]

- (1) NVR DNS was set to "Auto"
- (2) Entered the Router DNS IP incorrectly.
- (3) The external domain was inaccessible
- (4) DDNS connection failed



4. Measures

- Precautions for DNS IP settings
 - ① Auto : Recheck the router DNS IP address
 - ② Manual: Set the correct DNS server IP address (e.g. 168.126.63.1 / 8.8.8.8, etc.)

HDD not detected after NVR delivery


No.	# 9	Product Line	NVR
Product(Model)	XRN-3210RB2	Keyword	HDD tray being opened, HDD undetectability

1. Installation Cases

- The product equipped with NVR HDD was delivered by courier

2. Symptoms

- The HDD wasn't detected, and the HDD bracket was open.



3. Causes :

- The product was delivered with its HDD installed.

4. Measures

- When delivering the NVR product, pack and transport the NVR and HDD separately to prevent damage.
- Do not move the product with the HDD installed.

Delivering the product with its HDD installed is not covered by our product warranty.

- Product design and shipment are verified and guaranteed under basic installation or NO-HDD conditions.
- In addition to the HDD tray being opened, there may be problems such as HDD undetectability, device deformation, and RAID recognition error.